

[illegible]

FIG. 1




FIG. 2




FIG. 3




FIG. 4





FIG. 5



2025 RELEASE UNDER E.O. 14176



FIG. 6




FIG. 7




FIG. 8






FIG. 8A









sloped back of piston may extend to the face or top of the preceding piston

FIG. 9



ROTATIONAL SEQUENCE



200301322E4160

FIG. 16







FIG. 17






FIG. 18




FIG. 20




FIG. 19




FIG. 21




FIG. 22

1969-07-15 13:23:10

FIG. 23




FIG. 24




FIG. 25




FIG. 26




FIG. 27




FIG. 28




FIG. 29




FIG. 30

